

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
FER	Huger, SC	2008276	HRP&O	.069	38.000		32,526	CS-B	68	.069	.069	No Visible Defects
DSP	Detroit, MI	2007932	HRP&O	.077	63.560		33,930	DS	0	.076	.076	Subject to Rust Patches
DSP	Detroit, MI	2008255	HRP&O	.0787	63.625		31,505	DS	62	.077	.078	No Visible Defects
DSP	Detroit, MI	2008136	HRP&O	.0787	63.690		36,285	DS	62	.078	.078	Subject to Lite Patchy Rust
DSP	Detroit, MI	2008254	HRP&O	.0787	63.750		40,500	DS	62	.078	.078	No Visible Defects
DSP	Detroit, MI	2008311	HRP&O	.0787	63.750		35,210	DS	62	.082	.077	Subject to Light Patchy Rust
DSP	Detroit, MI	2008312	HRP&O	.0787	63.750		36,060	DS		.083	.078	Subject to Light Patchy Rust
DSP	Detroit, MI	2008135	HRP&O	.081	63.810		42,740	DS	62	.080	.080	Subject to Lite Patchy Rust
ALS	Spartanburg, SC	2005961	HRP&O	.090	50.151		21,900	CS-B	62	.090	.090	Subject to Rust
GPM	Franklin, OH	2007043	HRP&O	.0906	53.750		38,280	RB90	90	.086	.0915	Subject to Full Center
APL	Cleveland, OH	2006912	HRP&O	.093	42.875		13,170	GR36		.093	.094	Excess Prime (C1020 - Grade 36)
APL	Cleveland, OH	2006913	HRP&O	.093	42.875		12,675	GR36		.093	.094	Excess Prime (C1020 - Grade 36)
FER	Huger, SC	2008067	HRP&O	.093	48.000		42,233	CS-B	68	.093	.093	Subject to Solution Stain (Temper
FER	Huger, SC	2008090	HRP&O	.093	48.000		30,260	CS-B	68	.093	.093	Subject to Solution Stain
JMH	Huger, SC	2007980	HRP&O	.093	48.125		42,090	CS-B	68	.100	.095	Subject to Rinse Stain
JMH	Huger, SC	2007981	HRP&O	.093	48.125		41,400	CS-B	68	.094	.096	Subject to Rinse Stain
FER	Huger, SC	2007329	HRP&O	.093	48.250		42,665	CS-B	68	.093	.092	Subject to Speck Rust
FER	Huger, SC	2007330	HRP&O	.093	48.250		42,388	CS-B	68	.094	.093	Subject to Speck Rust
FER	Huger, SC	2007849	HRP&O	.093	59.750		34,250	CS-B	62	.093	.093	Subject to Solution Stain (Temper
FER	Huger, SC	2007852	HRP&O	.093	59.750		38,550	CS-B	62	.093	.093	Subject to Solution Stain (Temper
MPC	Gary, IN	2007192	HRP&O	.097	37.705		8,677	GR70		.097	.097	Subject to Rolled in Scale
MPC	Gary, IN	2007193	HRP&O	.097	37.705		8,544	GR70		.097	.097	Subject to Rolled in Scale
FER	Huger, SC	2007533	HRP&O	.097	48.875		25,230	CS-B	68	.097	.097	Subject to Water Stain
OLW	Winder, GA	2007742	HRP&O	.097	60.000		15,640	CS-B	68	.097	.097	Subject to Wavy Edges
HTW	Bristol, PA	2008130	HRP&O	.099	52.062		26,665	HSLA	83	.099	.099	No Visible Defects
GPM	Franklin, OH	2007528	HRP&O	.110	50.000		27,650	HSLA	76	.110	.108	No Visible Defects
ALS	Spartanburg, SC	2008125	HRP&O	.110	50.063		39,020	DS	61	.110	.110	No Visible Defects

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
ALS	Spartanburg, SC	2008123	HRP&O	.110	50.250		43,090	DS	63	.110	.110	No Visible Defects
ALS	Spartanburg, SC	2008120	HRP&O	.110	50.500		44,700	DS	55	.110	.110	No Visible Defects
NMS	Huger, SC	2007632	HRP&O	.111	36.000		14,380	CS-B	68	.120	.120	Subject to Stain
HSG	Grandville, MI	2007507	HRP&O	.111	36.875		34,020	GR60		.111	.111	Cut out in center of coil
FER	Huger, SC	2007832	HRP&O	.111	60.000		42,444	CS-B	62	.111	.111	Subject to Chatter
FER	Huger, SC	2008197	HRP&O	.111	60.000		42,997	CS-B	62	.111	.111	Subject to Edge Wave
ALS	Spartanburg, SC	2008001	HRP&O	.111	60.063		16,080	CS-B	62	.112	.112	Subject to Wavy Edges
FER	Huger, SC	2007202	HRP&O	.112	48.000		31,900	CS-B	62	.112	.112	No Visible Defects
FER	Huger, SC	2008237	HRP&O	.112	48.620		23,590	CS-B	69	.114	.114	No Visible Defects
ALS	Spartanburg, SC	2008316	HRP&O	.1197	40.500		21,985	DS	50	.1197	.1197	Subject to Rinse Stain
ALS	Spartanburg, SC	2008128	HRP&O	.1197	40.550		24,620	DS	50	.1197	.1197	Subject to Solution Stain
MSD	Trinity, AL	2007313	HRP&O	.124	42.500		22,640	CS-B	81	.132	.132	Subject to Light Stain
FER	Huger, SC	2007702	HRP&O	.1245	60.000		47,520	GR70	87	.1245	.1245	Subject to Wavy Edges
ALS	Spartanburg, SC	2008279	HRP&O	.125	48.250		44,875	CS-B		.127	.126	Light Rust
MPC	Gary, IN	2007209	HRP&O	.1265	36.312		14,180	CS-B		.1258	.131	Subject to Lite Laminations
FER	Huger, SC	2008072	HRP&O	.127	38.600		8,745	CS-B	62	.127	.127	No Visible Defects
JMH	Huger, SC	2007983	HRP&O	.127	38.625		8,770	CS-B	62	.125	.125	No Visible Defects
JMH	Huger, SC	2007984	HRP&O	.127	38.625		8,980	CS-B	62	.125	.125	No Visible Defects
JMH	Huger, SC	2007985	HRP&O	.127	38.625		8,850	CS-B	62	.125	.125	No Visible Defects
FER	Huger, SC	2007947	HRP&O	.127	48.000		46,280	CS-B	62	.127	.127	Subject to Water Stain
FER	Huger, SC	2008257	HRP&O	.129	48.250		44,640	HSLA	81	.129	.129	No Visible Defects
FER	Huger, SC	2008258	HRP&O	.129	48.250		46,580	HSLA	81	.129	.129	No Visible Defects
JMH	Huger, SC	2008248	HRP&O	.129	49.500		46,320	HSLA	81	.130	.127	No Visible Defects
FER	Huger, SC	2007462	HRP&O	.148	55.125		45,840	DS	46	.147	.148	No Visible Defects
FER	Huger, SC	2007461	HRP&O	.148	55.500		42,040	DS	49	.146	.148	No Visible Defects
APL	Cleveland, OH	2008314	HRP&O	.152	48.300		21,410	DS		.150	.150	Excess Prime
JMH	Huger, SC	2001802	HRP&O	.152	50.750		16,470	GR60	82	.152	.152	Subject to Wave/Oscillated

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
COL	Atlanta, GA	2001805	HRP&O	.157	62.750		16,485	FH	95	.160	.160	Excess Prime (Full Hard - Storage)
FER	Huger, SC	2008025	HRP&O	.170	41.625		35,712	DS	50	.170	.170	Subject to Rust
COL	Atlanta, GA	2006939	HRP&O	.171	43.250		40,440	DDS	55	.177	.171	No Visible Defects
COL	Atlanta, GA	2006942	HRP&O	.171	43.250		39,910	DDS	52	.173	.176	No Visible Defects
COL	Atlanta, GA	2006945	HRP&O	.171	43.250		41,000	DDS	55	.174	.177	No Visible Defects
FER	Huger, SC	2007949	HRP&O	.188	48.000		42,009	CS-B	62	.188	.188	No Visible Defects
FER	Huger, SC	2008266	HRP&O	.188	48.000		39,840	CS-B	62	.188	.188	No Visible Defects
FER	Huger, SC	2008244	HRP&O	.2233	51.500		50,760	CS-B	66	.2233	.2233	No Visible Defects
FER	Huger, SC	2008243	HRP&O	.225	57.500		29,900	CS-B	66	.225	.225	No Visible Defects
FER	Huger, SC	2008247	HRP&O	.225	57.500		29,705	CS-B	66	.225	.225	No Visible Defects
FER	Huger, SC	2007699	HRP&O	.229	37.000		19,085	CS-B	70	.229	.229	Subject to Minor Surface Cracks
FER	Huger, SC	2007701	HRP&O	.229	37.000		23,494	CS-B	70	.229	.229	Subject to Minor Surface Cracks
FER	Huger, SC	2008241	HRP&O	.240	50.500		47,240	DS	50	.240	.240	No Visible Defects
FER	Huger, SC	2008336	HRP&O	.240	60.000		32,444		81	.240	.240	No Visible Defects
MPC	Gary, IN	2006334	HRP&O	.265	52.562		30,630	GR70	89	.265	.265	Subject to Pits (C1024)
NMS	Huger, SC	2007869	HRP&O	.302	66.000		44,940	HSLA	84	.302	.302	Subject to Stain
FER	Huger, SC	2007499	HRP&O	.306	60.000		36,477	C1020	77	.306	.306	No Visible Defects (C1020)
JMH	Huger, SC	2005904	HRP&O	.363	40.375		34,600	CS-B	70	.366	.363	No visible Defects
FER	Huger, SC	2006706	HRP&O	.365	48.000		40,264	HSLA	84	.365	.365	No Visible Defects
FER	Huger, SC	2007362	HRP&O	.365	60.000		39,172	C1020	77	.365	.365	No Visible Defects (C1020)
FER	Huger, SC	2007365	HRP&O	.365	60.000		42,196	C1020	77	.365	.365	No Visible Defects (C1020)
FER	Huger, SC	2007888	HRP&O	.365	60.000		32,312	C1020	77	.365	.365	Subject to Minor Surface Cracks