

Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
DSP	Detroit, MI	2006755	HRP&O	.076	14.625		7,215	GR80	72	.078	.078	No Visible Defects
JMH	Huger, SC	2007998	HRP&O	.0795	17.000		9,300	CS-B	68	.082	.082	Subject to Wavy Edges
FER	Huger, SC	2008078	HRP&O	.0795	20.750		4,725	CS-B	68	.0795	.0795	No Visible Defects
COL	Atlanta, GA	2004466	HRP&O	.080	2.500		2,256	HSLA	83	.0800	.0800	No Visible Defects (2 Coils)
ALM	Cartersville, GA	2004467	HRP&O	.083	1.500		1,210	N/A		.081	.081	No Visible Defects (2 Coils)
MPC	Gary, IN	2006760	HRP&O	.084	10.300		9,435	CS-B	65	.086	.086	Subject to Laminations and Scale
PRK	Kenton, OH	2007743	HRP&O	.087	10.709		4,285	DS	65	.087	.087	Subject to Scratches
PRK	Kenton, OH	2007744	HRP&O	.087	10.709		4,285	DS	65	.087	.087	Subject to Scratches
PRK	Kenton, OH	2007745	HRP&O	.087	10.709		4,285	DS	65	.087	.087	Subject to Scratches
ALS	Spartanburg, SC	2008122	HRP&O	.088	6.600		5,635	DS		.088	.088	Excess Prime
ALM	Cartersville, GA	2004468	HRP&O	.090	1.500		620	N/A		.0900	.0900	No Visible Defects
APL	Cleveland, OH	2006910	HRP&O	.093	7.062		4,228	GR36		.093	.096	No Visible Defects (2 Coils -
APL	Cleveland, OH	2006911	HRP&O	.093	7.062		4,266	GR36		.093	.098	No Visible Defects (2 Coils -
LSM	Anderson, SC	2007679	HRP&O	.097	1.000		350	CS-B	68	.097	.097	Rust Throughout (2 Coils)
LSM	Anderson, SC	2007678	HRP&O	.0970	4.250		1,510	CS-B	68	.097	.097	Rust Throughout (2 Coils)
LSM	Anderson, SC	2007680	HRP&O	.097	11.250		3,990	CS-B	68	.097	.097	Rust Throughout
COL	Atlanta, GA	2008220	HRP&O	.097	21.500		9,935	DS	50	.095	.097	No Visible Defects
COL	Atlanta, GA	2008221	HRP&O	.097	21.500		9,215	DS	50	.100	.097	No Visible Defects
COL	Atlanta, GA	2008223	HRP&O	.097	21.500		9,870	DS	50	.096	.098	No Visible Defects
COL	Atlanta, GA	2008224	HRP&O	.097	21.500		9,185	DS	50	.096	.098	No Visible Defects
COL	Atlanta, GA	2008234	HRP&O	.097	21.500		9,870	DS	50	.112	.094	No Visible Defects
COL	Atlanta, GA	2008235	HRP&O	.097	21.500		9,265	DS	50	.099	.096	No Visible Defects
OLW	Winder, GA	2008322	HRP&O	.0972	12.187		1,645	CS-B	62	.0972	.0972	No Visible Defects
OLW	Winder, GA	2008323	HRP&O	.0972	12.187		1,645	CS-B	62	.0972	.0972	No Visible Defects
OLW	Winder, GA	2008324	HRP&O	.0972	12.187		1,645	CS-B	62	.0972	.0972	No Visible Defects
OLW	Winder, GA	2008325	HRP&O	.0972	12.187		1,645	CS-B	62	.0972	.0972	No Visible Defects
COL	Atlanta, GA	2006033	HRP&O	.098	5.000		3,460	GR50	81	.098	.098	No Visible Defects

Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
ALS	Spartanburg, SC	2008124	HRP&O	.110	7.000		5,140	DS	55	.110	.110	No Visible Defects (7 Coils)
GPM	Franklin, OH	2007216	HRP&O	.110	8.000		3,960	DS	60	.115	.113	Subject to Water Stain (Bundled)
GPM	Franklin, OH	2007217	HRP&O	.110	8.000		3,960	DS	60	.115	.113	Subject to Water Stain (Bundled)
GPM	Franklin, OH	2007218	HRP&O	.110	8.000		3,620	DS	60	.112	.111	Subject to Water Stain
GPM	Franklin, OH	2007529	HRP&O	.110	12.375		3,230	HSLA	76	.110	.111	No Visible Defects
GPM	Franklin, OH	2007530	HRP&O	.110	12.375		3,220	HSLA	76	.111	.111	No Visible Defects
OLW	Winder, GA	2008180	HRP&O	.123	19.188		6,740	CS-B	68	.126	.126	No Visible Defects
MSD	Trinity, AL	2007314	HRP&O	.124	11.180		3,040	CS-B	81	.132	.132	Subject to Light Stain
COL	Atlanta, GA	2003473	HRP&O	.156	3.625		4,940	CS-B	60	.1580	.1580	No Visible Defects (13 Coils)
SMP	Lawrenceville, GA	2004646	HRP&O	.172	1.500		1,260	CS-B	62	.1710	.1709	No Visible Defects (2 Coils)
FER	Huger, SC	2008079	HRP&O	.172	11.750		3,625	HSLA	79	.172	.172	No Visible Defects
FER	Huger, SC	2008080	HRP&O	.172	11.750		3,750	HSLA	79	.172	.172	No Visible Defects
FER	Huger, SC	2008081	HRP&O	.172	11.750		3,685	HSLA	79	.172	.172	No Visible Defects
CHI	Gary, IN	2007014	HRP&O	.175	3.116		2,645	HSLA		.177	.177	Subject to Pits and Dents
CHI	Gary, IN	2007012	HRP&O	.175	16.375		4,435	HSLA		.178	.178	Subject to Pits and Dents
CHI	Gary, IN	2007013	HRP&O	.175	16.375		3,480	HSLA		.180	.180	Subject to Pits and Dents
JMH	Huger, SC	2005721	HRP&O	.197	17.500		11,570	C1038	88	.201	.202	No Visible Defects (C1040)
JMH	Huger, SC	2005722	HRP&O	.197	18.500		11,900	C1038	88	.202	.201	No Visible Defects (C1040)
JMH	Huger, SC	2005731	HRP&O	.197	18.500		11,930	C1038	88	.203	.201	No Visible Defects (1040)