

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
GPM	Franklin, OH	2005139	HRP&O	.083	51.750		47,900	DS	50	.081	.081	Subject to Pickle Stain and
COL	Atlanta, GA	2004421	HRP&O	.095	30.000		19,500	HS		.100	.100	No Visible Defects
CHI	Gary, IN	2003286	HRP&O	.095	56.000		47,460	HS	78	.097	.098	No Visible Defects
JMH	Huger, SC	2004853	HRP&O	.096	53.250		42,060	CS-B	68	.093	.091	No Visible Defects
JMH	Huger, SC	2004953	HRP&O	.100	48.250		40,680	CS-B	68	.098	.095	No Visible Defects
COL	Atlanta, GA	2001798	HRP&O	.100	57.000		17,515	HS	85	.106	.107	No Visible Defects
CHI	Gary, IN	2005224	HRP&O	.102	51.810		40,520	DS	55	.107	.103	Heavy Rust Throughout
COL	Atlanta, GA	2005037	HRP&O	.105	51.250		38,770	DS	55	.104	.107	No visible Defects (Storage Rust)
JMH	Huger, SC	2004775	HRP&O	.108	59.750		39,520	CS-B	62	.110	.110	No Visible Defects
JMH	Huger, SC	2005082	HRP&O	.111	60.000		40,890	CS-B	62	.111	.109	No Visible Defects
JMH	Huger, SC	2005205	HRP&O	.112	54.375		16,720	DS	50	.112	.106	No Visible Defects
VOS	Jeffersonville, IN	2004232	HRP&O	.114	56.400		13,780	HS		.114	.114	No Visible Defects
JMH	Huger, SC	2005023	HRP&O	.125	60.000		47,050	CS-B	67	.125	.129	No Visible Defects
TRC	Wilmerding, PA	2004748	HRP&O	.126	36.500		30,360	CS-B		.131	.131	Storage Rust; Balance NVD
JMH	Huger, SC	2005117	HRP&O	.127	63.625		25,470	DS	50	.125	.123	Subject to Rust
JMH	Huger, SC	2003896	HRP&O	.142	42.062		26,470	CS-B	62	.142	.142	No Visible Defects
ALM	Cartersville, GA	2003468	HRP&O	.145	49.625		41,340	CS-B	60	.1450	.148	Storage Rust
VOS	Jeffersonville, IN	2003524	HRP&O	.150	49.929		28,890	CS-B	69	.149	.149	No Visible Defects
COL	Atlanta, GA	2001694	HRP&O	.152	50.750		30,750	HS	83	.157	.156	No Visible Defects
COL	Atlanta, GA	2001802	HRP&O	.152	50.750		20,850	HS	82	.152	.152	N/A
JMH	Huger, SC	2004753	HRP&O	.152	60.625		42,360	DS	50	.149	.145	No Visible Defects
COL	Atlanta, GA	2004751	HRP&O	.153	52.625		41,650	DDS	34	.151	.150	No Visible Defects
COL	Atlanta, GA	2001010	HRP&O	.157	50.500		30,220	HS	80	.1600	.1600	Telescoped ID
COL	Atlanta, GA	2001806	HRP&O	.157	62.500		15,395	HS	95	.160	.160	Excess Prime (Storage Rust)
COL	Atlanta, GA	2001805	HRP&O	.157	62.750		16,485	HS	90	.160	.160	Excess Prime (Storage Rust)
COL	Atlanta, GA	2001672	HRP&O	.160	57.125		44,600	HS	81	.166	.160	No Visible Defects
CHI	Gary, IN	2004714	HRP&O	.165	39.750		18,470	HS	86	.169	.172	Excess Prime

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
CHI	Gary, IN	2004715	HRP&O	.165	39.750		18,430	HS	86	.168	.170	Excess Prime
JMH	Huger, SC	2005013	HRP&O	.169	48.250		29,520	CS-B	67	.175	.166	No Visible Defects
JMH	Huger, SC	2005010	HRP&O	.169	60.375		56,900	CS-B	67	.176	.168	No Visible Defects
JMH	Huger, SC	2005138	HRP&O	.171	48.500		41,850	CS-B	62	.174	.171	No Visible Defects
JMH	Huger, SC	2004730	HRP&O	.200	50.500		13,320	DS	50	.200	.200	No Visible Defects
JMH	Huger, SC	2004902	HRP&O	.229	37.125		33,040	HS		.228	.228	No Visible Defects
JMH	Huger, SC	2004901	HRP&O	.238	48.500		32,737	CS-B	66	.238	.235	No Visible Defects
JMH	Huger, SC	2004903	HRP&O	.238	48.500		46,840	CS-B	66	.234	.234	No Visible Defects
JMH	Huger, SC	2004904	HRP&O	.238	48.500		46,970	CS-B	66	.238	.235	No Visible Defects
JMH	Huger, SC	2005014	HRP&O	.238	60.000		16,990	CS-B	66	.244	.239	No Visible Defects
JMH	Huger, SC	2004905	HRP&O	.238	60.625		48,020	CS-B	59	.240	.238	No Visible Defects
JMH	Huger, SC	2004564	HRP&O	.363	60.500		32,080	CS-B	59	.363	.361	No Visible Defects
COL	Atlanta, GA	2003696	HRP&O	.364	60.500		39,100	HSLA	81	.371	.367	No Visible Defects