

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location		Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection
WMC	Atlanta, GA	2008182	HRP&O	.069	19.750	90.000	3,072	CS-B	62		.067	No Visible Defects
WMC	Atlanta, GA	2008183	HRP&O	.069	19.750	90.000	3,072	CS-B	62		.067	No Visible Defects
WMC	Atlanta, GA	2008184	HRP&O	.069	19.750	90.000	1,036	CS-B	62		.067	No Visible Defects
WMC	Atlanta, GA	2008181	HRP&O	.069	60.000	120.000	4,420	CS-B	62		.067	No Visible Defects
WMC	Atlanta, GA	2008185	HRP&O	.069	60.000	120.000	2,350	CS-B	62		.0747	No Visible Defects
WMC	Atlanta, GA	2008186	HRP&O	.07	60.000	144.000	4,512	CS-B	68		.0747	Subject to Speck Rust
JMA	Blytheville, AR	2007465	HRP&O	.071	60.250	34.380	2,475	CS-B	81		.075	No Visible Defects
JMA	Blytheville, AR	2007466	HRP&O	.071	60.250	34.380	2,475	CS-B	81		.075	No Visible Defects
APL	Cleveland, OH	2006559	HRP&O	.083	48.000	120.000	2,600	CS-B	62		.083	No Visible Defects
COL	Atlanta, GA	2008228	HRP&O	.093	48.000	96.000	3,541	CS-B	68		.093	No Visible Defects
COL	Atlanta, GA	2008229	HRP&O	.093	48.000	96.000	3,668	CS-B	68		.093	No Visible Defects
COL	Atlanta, GA	2008230	HRP&O	.093	48.000	96.000	3,668	CS-B	68		.093	No Visible Defects
COL	Atlanta, GA	2008231	HRP&O	.093	48.000	96.000	3,668	CS-B	68		.093	No Visible Defects
COL	Atlanta, GA	2008232	HRP&O	.093	48.000	96.000	3,668	CS-B	68		.093	No Visible Defects
COL	Atlanta, GA	2008233	HRP&O	.093	48.000	96.000	3,668	CS-B	68		.093	No Visible Defects
GSM	Acworth, GA	2008267	HRP&O	.100	60.000	120.000	3,680	CS-B	68		.100	No Visible Defects
GSM	Acworth, GA	2008268	HRP&O	.1	60.000	120.000	3,470	CS-B	68		.100	No Visible Defects
APL	Cleveland, OH	2005895	HRP&O	.102	36.000	96.000	1,000	DS			.102	No Visible Defects
FER	Huger, SC	2008138	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008139	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008140	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008141	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008142	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008143	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008144	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008145	HRP&O	.108	48.000	74.000	3,905	CS-B	68		.108	No Visible Defects
FER	Huger, SC	2008076	HRP&O	.108	48.000	74.312	3,905	CS-B	68		.108	No Visible Defects

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection
FER	Huger, SC	2008073	HRP&O	.108	48.000	74.375	3,905	CS-B	68	.108	No Visible Defects
FER	Huger, SC	2008074	HRP&O	.108	48.000	74.375	3,905	CS-B	68	.108	No Visible Defects
FER	Huger, SC	2008075	HRP&O	.108	48.000	74.375	3,905	CS-B	68	.108	No Visible Defects
FER	Huger, SC	2008196	HRP&O	.111	60.000	90.000	4,223	CS-B	62	.111	No Visible Defects
ALS	Spartanburg, SC	2008126	HRP&O	.1197	40.550	18.000	1,790	DS	50	.1197	Subject to Solution Stain
ALS	Spartanburg, SC	2008127	HRP&O	.1197	40.550	18.000	2,685	DS		.1197	Subject to Solution Stain
MPC	Gary, IN	2007210	HRP&O	.1265	36.375	72.125	2,770	CS-B		.1265	Subject to Lite Laminations
NMS	Huger, SC	2006513	HRP&O	.151	60.025	120.125	2,470	CS-B	68	.149	No Visible Defects
APL	Cleveland, OH	2008313	HRP&O	.152	48.000	120.000	3,288	DS		.155	Excess Prime
NMS	Huger, SC	2005288	HRP&O	.154	59.000	118.000	2,822	C1020	75	.154	No Visible Defects
COL	Atlanta, GA	2002570	HRP&O	.156	48.000	120.125	790	CS-B	66	.157	No Visible Defects
COL	Atlanta, GA	2002569	HRP&O	.156	48.125	120.125	4,010	CS-B	66	.159	No Visible Defects
FER	Huger, SC	2007834	HRP&O	.169	37.000	120.000	4,413	CS-B	81	.169	No Visible Defects
NMS	Huger, SC	2008317	HRP&O	.169	60.000	120.000	6,375	CS-B	81	.169	No Visible Defects
NMS	Huger, SC	2008319	HRP&O	.169	60.000	120.000	6,375	CS-B	81	.169	No Visible Defects
FER	Huger, SC	2008199	HRP&O	.172	60.000	120.000	2,625	HSLA	81	.172	No Visible Defects
NMS	Huger, SC	2007827	HRP&O	.229	37.000	117.000	2,371	CS-B		.2317	No Visible Defects
FER	Huger, SC	2008332	HRP&O	.240	60.000	120.000	3,999	HSLA	81	.240	No Visible Defects
FER	Huger, SC	2008333	HRP&O	.240	60.000	120.000	3,999	HSLA	81	.240	No Visible Defects
FER	Huger, SC	2008334	HRP&O	.240	60.000	120.000	3,999	HSLA	81	.240	No Visible Defects
FER	Huger, SC	2008335	HRP&O	.240	60.000	120.000	3,999	HSLA	81	.240	No Visible Defects
FER	Huger, SC	2008198	HRP&O	.302	60.000	96.000	3,573	HSLA	81	.302	No Visible Defects
NMS	Huger, SC	2008274	HRP&O	.363	60.000	120.000	5,362	HSLA	72	.363	No Visible Defects
NMS	Huger, SC	2008275	HRP&O	.363	60.000	120.000	5,362	HSLA	72	.363	No Visible Defects
COL	Atlanta, GA	2007363	HRP&O	.365	60.000	72.000	2,282	C1020	77	.365	No Visible Defects (C1020)
COL	Atlanta, GA	2007364	HRP&O	.365	60.000	72.000	2,282	C1020	77	.365	No Visible Defects (C1020)
COL	Atlanta, GA	2007366	HRP&O	.365	60.000	72.000	2,273	C1021	87	.365	No Visible Defects (C1021)

# Sun States Inventory

Click Browser "Back" Button to Return to Website

Plant Location	Tag #	Product	Gauge	Width	Length	Weight	Grade	Rb	ID	OD	Visual Inspection	
COL	Atlanta, GA	2007367	HRP&O	.365	60.000	72.000	2,273	C1021	87		.365	No Visible Defects (C1021)
COL	Atlanta, GA	2007368	HRP&O	.365	60.000	72.000	2,273	C1021	87		.365	No Visible Defects (C1021)
COL	Atlanta, GA	2005217	HRP&O	.365	60.000	96.000	6,101	HSLA	81		.375	No Visible Defects
COL	Atlanta, GA	2005768	HRP&O	.365	60.000	96.000	4,290	HSLA	81		.375	No Visible Defects
COL	Atlanta, GA	2006350	HRP&O	.365	60.000	96.000	3,034	HSLA	81		.375	No Visible Defects
NMS	Huger, SC	2008318	HRP&O	.365	60.000	129.000	6,894	HS	77		.365	No Visible Defects (C1020)